


## Steelclutch plate all models 1983 up



Steel clutch plate for all Maico models 1983 up till today. 6 pieces are needed together with a mixed sinter and organic system. For a cpl. organic system you have to use 5 pieces. A full sintered 6 spring clutch system needs 7 pieces!

Rating: Not Rated Yet

**Price**

14,90 €

14,90 €

Sales price without tax 12,52 €

Discount

Tax amount 2,38 €

[Ask a question about this product](#)

Manufacturer [Maico](#)